



























STEP UP
הצעד הראשון לעיצוב הבית







BY-ET3074




Parts List

<p>①</p>  <p>x1</p>	<p>②</p>  <p>x1</p>	<p>③</p>  <p>x1</p>	<p>④</p>  <p>x1</p>
<p>⑤</p>  <p>x1</p>	<p>⑥</p>  <p>x2</p>	<p>⑦</p>  <p>x2</p>	<p>⑧</p>  <p>x2</p>
<p>⑨</p>  <p>x2</p>	<p>⑩</p>  <p>x2</p>	<p>⑫</p>  <p>x2</p>	<p>⑬</p>  <p>x2</p>


Hardware List

<p>A</p>  <p>φ8x30mm x8</p>	<p>B</p>  <p>x12</p>	<p>C</p>  <p>x12</p>	<p>D</p>  <p>4x35mm x8</p>	<p>E</p>  <p>3x12mm x28</p>
<p>F</p>  <p>3x16mm x4</p>	<p>G</p>  <p>x4</p>	<p>H</p>  <p>7x40mm x4</p>	<p>I</p>  <p>M6x35mm x4</p>	<p>J</p>  <p>M6x25mm x6</p>
<p>K</p>  <p>x2</p>	<p>L</p>  <p>x1</p>	<p>M</p>  <p>x1</p>		
<p>DL</p>  <p>x2</p>	<p>DR</p>  <p>x2</p>	<p>CL</p>  <p>x2</p>	<p>CR</p>  <p>x2</p>	


Step 1



x2


<p>A</p>  <p>φ8x30mm x4</p>	<p>B</p>  <p>x8</p>	<p>M</p>  <p>x1</p>
---	---	---

Step 2




x2

Step 3




x2


Step 4




x2




Step 5




x2




Step 6




x2






Step 7




<p>A</p>  <p>φ8x30mm</p> <p>x2</p>	<p>B</p>  <p>x4</p>	<p>M</p>  <p>x1</p>
---	--	--



Step 8




<p>K</p>  <p>x1</p>	<p>E</p>  <p>3x12mm</p> <p>x2</p>	<p>M</p>  <p>x1</p>
---	---	---


Step 9




<p>K</p>  <p>x1</p>	<p>E</p>  <p>3x12mm</p>	<p>M</p>  <p>x2</p>
--	---	--



Step 10





<p>CR</p>  <p>x2</p>	<p>E</p>  <p>3x12mm</p>	<p>M</p>  <p>x1</p>
---	---	---


Step 11






CL	E	M
		
x2	3x12mm	x6
		x1

Step 12





C	M
	
x2	x1



Step 13





Step 14





Step 15




Step 16



Step 19



G  x4	F  3x16mm x4	M  x1
---	---	--

Step 20

