






STEP UP
הצעד הראשון לעיצוב הבית

BY-ET3284




Parts List

①




x1

②




x1

③




x1

④




x1

⑤




x1

⑥




x1

⑦




x1

⑧




x1

⑨




x1

⑩




x1

⑪




x1

⑫




x2

⑬
















x2

⑭










x2








Hardware List

<p>A</p>  <p>φ8x30mm x6</p>	<p>B</p>  <p>x12</p>	<p>C</p>  <p>x12</p>	<p>D</p>  <p>x1</p>
<p>E</p>  <p>4# x1</p>	<p>F</p>  <p>φ4x35mm x4</p>	<p>G</p>  <p>φ3x16mm x4</p>	<p>H</p>  <p>φ3x12mm x12</p>
<p>I</p>  <p>M6x25mm x4</p>	<p>J</p>  <p>M6x35mm x8</p>	<p>K</p>  <p>M6x25mm x4</p>	<p>L</p>  <p>x4</p>
<p>M</p>  <p>x4</p>	<p>N</p>  <p>x4</p>	<p>O</p>  <p>3# x1</p>	<p>P</p>  <p>x4</p>
<p>DL</p>  <p>x1</p>	<p>DR</p>  <p>x1</p>	<p>CL</p>  <p>x1</p>	<p>CR</p>  <p>x1</p>


Step 1




Step 2





Step 3





Step 4




Step 5



Step 6




Step 7



I  M6x25mm x4	E  4# x1
--------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------


Step 8




K  M6x25mm x4	O  3# x1
---------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------

x2



Step 9







Step 10




Step 11




Step 12






Step 13






Step 14




Step 15





Step 16




Step 17






<p>H</p>  <p>φ3x12mm x6</p>	<p>D</p>  <p>x1</p>	<p>DL</p>  <p>x1</p>	<p>DR</p>  <p>x1</p>
--------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------

Step 18



Step 19



Step 20

