






STEP UP
הצעד הראשון לעיצוב הבית

BY-ET3283




Parts List

①




x1

②




x1

③




x1

④




x1

⑤



x1

⑥



x1

⑦




x1

⑧




x1

⑨




x2

⑩




x2

⑪




x2

⑫




x1

⑬




x1

⑭




x1

⑮




x1

⑯




x1

⑰



x2

⑱

















x2

⑲






x4


Hardware List

<p>A</p>  <p>φ8x30mm x17</p>	<p>B</p>  <p>x38</p>	<p>C</p>  <p>x38</p>	<p>D</p>  <p>x1</p>
<p>E</p>  <p>x1</p>	<p>F</p>  <p>φ4x35mm x4</p>	<p>G</p>  <p>φ3x12mm x14</p>	<p>H</p>  <p>φ3x16mm x4</p>
<p>I</p>  <p>φ7x40mm x4</p>	<p>J</p>  <p>M6x30mm x8</p>	<p>K</p>  <p>M6x35mm x4</p>	<p>L</p>  <p>x4</p>
<p>M</p>  <p>x1</p>	<p>N</p>  <p>x28</p>	<p>O</p>  <p>x4</p>	
<p>DL</p>  <p>x1</p>	<p>DR</p>  <p>x1</p>	<p>CL</p>  <p>x1</p>	<p>CR</p>  <p>x1</p>

Step 1




x1




φ8x30mm

x2




x4


Step 2





Step 3






Step 4






F  φ4x35mm x4	D  x1
---------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------




Step 5





Step 6





Step 7




Step 8




Step 9



φ8x30mm x2





M6x35mm x2




x1


Step 10



x1





φ3x12mm x3





x1



Step 11




Step 12



Step 13




x1





φ3x12mm

x3




x1

Step 14




x1




φ8x30mm

x1




x2



Step 15





Step 16




Step 17




Step 18




Step 19




Step 20




Step 21





φ8x30mm x2





φ7x40mm x4




x1




Step 22






M6x30mm x8




x1



Step 23




x1






φ8x30mm

x4




x8

Step 24




x1




x16

x4


Step 25




D  x1
C  x8




x2

Step 26



D  x1
C  x8

Step 27



Step 28

