







STEP UP
הצעד הראשון לעיצוב הבית

BY-DC3252




Parts List

①




x1

②




x1

③




x1

④



x1

⑤




x1

⑥




x1

⑦




x2

⑧




x1

⑨




x4

⑩




x4

⑪




x8

⑫




x8

⑬




x8

⑭




x8

⑮




x8

⑯























x4

⑰




x1


Hardware List

A  φ8x30mm x20	B  x46	C  x46	D  x1
E  x1	F  φ4x35mm x42	G  φ4x22mm x2	H  φ3x16mm x12
I  φ3.5x12mm x80	J  x2	K  x4	L  x2
M  x12	N  φ7x40mm x3	O  x8	P  M6x12mm x36
Q  M6x25mm x8	R  x5	S  x40	
DL  x8	DR  x8	CL  x8	CR  x8


Step 1



Step 2




Step 3




x8


Step 4





x8




Step 5




x8





x8






Step 7




I	D	CL
		
φ3.5x12mm x8	x1	x4

Step 8




I	D	CR
		
φ3.5x12mm x8	x1	x4

Step 9




A φ8x30mm x1	B x2	I φ3.5x12mm x8	CL x4	D x1
----------------------------	--------------------	------------------------------	---------------------	--------------------

Step 10




P M6x12mm x4	O x4	E x1
----------------------------	--------------------	--------------------

Step 11





A φ8x30mm x1	B x2	I φ3.5x12mm x8	CR x4	D x1
----------------------------	--------------------	------------------------------	---------------------	--------------------


Step 12




P M6x12mm x4	O x4	E x1
----------------------------	--------------------	--------------------




Step 15




Step 16





Step 17









Step 18




Step 19




Step 20




Step 21




Step 22




Step 23



Step 24



Step 25



Step 26

